

Wimbledon Park Lake Project - (Reservoir Safety and Desilting)

Summary of Technical Steering Group Meeting – 23 January 2018

Project Status

Discussions on Funding & Partnering Opportunities: The group reviewed and discussed possible funding bids. It was agreed that the group need to work on gaining clarity on potential costs for all aspects of the project whilst seeking out what opportunities might be available. A small group will start work to list all possibilities.

Programme of Activities

- Ecological Impact Assessment This is now out to tender on the London Portal
- Fish Study This has been commissioned and the study will take place in the next month
- Tree Matters Self-seeded saplings the plan for works is still to be agreed with and then implemented. Tree survey on the Wimbledon Club, LBM land and part of the Golf Course land is still to be developed as a joint commission, led by the AELTC on behalf of the group – this would only be of sufficient scope to support the lake improvement works.
- Flood Study The Flood Study brief is now live on the Merton portal for tendering. The brief is wider than the scope on the Section 10 Supervising Engineer Report and will also look at cost versus benefits. Closing date for tenders is February 5th 2018.
- Sluice Gate Matters Following a site meeting at the sluice gate it has been agreed that the area around the sluice gate needs clearing of self-seeded saplings, a fallen tree and leaf fall etc. Also at an appropriate time in the future a CCTV survey will need to be carried out of the outflow pipes.

Risk Register

Risk Description / Details:	Likelihood	Impact	Risk	Risk	Recommended Management Strategy and Response	Risk Owner	Likelihood	Impact	Risk	Residual Risk
Rising Costs of Works	3	4	12	н	Until reports are completed we cannot finalise a strategy	LBM	2	3	6	м
Failure to meet requirements under the Reservoir Act	4	4	16	н	Fulfil the actions and measures required and specified by panel engineer in the annual and S10 reports.	LBM	3	3	9	м
Section 10 Report – (10 yearly Report) – This could be brought forward at short notice	3	4	12	н	Carry out annual inspections by supervising engineer and monthly inspections by Flood Risk Officer - LBM	LBM	3	3	9	М