

Classified Vehicle Video Survey

Site: Cam 2 - Balfour Road/
Merton Road Junction
 Location: L.B. Merton
 Date: Monday 17th - Sunday
23rd November 2014
 Time: 0600 - 1800
 Weather: Changeable



Camera 2 Turning Movements



Summary of turning movements

1	P/C	M/C	Cars	LGV	MGV / HGV	Bus	Coach	Total
17/11/2014	2	5	411	110	23	0	2	553
20/11/2014	7	9	403	87	17	0	2	525
29/11/2014	3	11	433	51	4	0	0	503

2	P/C	M/C	Cars	LGV	MGV / HGV	Bus	Coach	Total
17/11/2014	2	3	179	48	8	5	2	247
20/11/2014	5	8	221	60	15	2	2	313
29/11/2014	4	5	177	25	2	0	0	213

Classified Vehicle Video Survey

Site: Cam 2 - Balfour Road/
Merton Road Junction
 Location: L.B. Merton
 Date: Monday 17th November 2014
 Time: 0600 - 1800
 Weather: Dry

1	P/C	M/C	Cars	LGV	MGV / HGV	Bus	Coach	Total
06:00	0	0	0	0	0	0	0	0
06:15	0	0	1	1	0	0	0	2
06:30	0	0	5	2	1	0	0	8
06:45	0	0	3	2	0	0	0	5
Total	0	0	9	5	1	0	0	15
07:00	0	0	6	1	0	0	0	7
07:15	0	0	14	7	1	0	0	22
07:30	0	0	25	1	1	0	1	28
07:45	0	0	19	5	1	0	0	25
Total	0	0	64	14	3	0	1	82
08:00	0	0	14	7	1	0	0	22
08:15	0	0	15	2	0	0	0	17
08:30	0	0	9	2	0	0	0	11
08:45	0	0	13	1	0	0	0	14
Total	0	0	51	12	1	0	0	64
09:00	0	0	11	2	1	0	0	14
09:15	0	0	11	2	0	0	0	13
09:30	0	0	12	3	1	0	0	16
09:45	0	0	7	5	1	0	0	13
Total	0	0	41	12	3	0	0	56
10:00	0	0	5	0	1	0	0	6
10:00	0	0	12	2	1	0	0	15
10:30	0	0	9	2	1	0	0	12
10:45	0	0	9	2	0	0	0	11
Total	0	0	35	6	3	0	0	44
11:00	0	0	7	6	0	0	0	13
11:15	0	0	7	2	0	0	0	9
11:30	1	0	7	1	1	0	0	10
11:45	1	0	4	2	2	0	0	9
Total	2	0	25	11	3	0	0	41
12:00	0	0	6	0	0	0	0	6
12:15	0	0	6	3	2	0	0	11
12:30	0	2	7	2	0	0	0	11
12:45	0	0	13	2	2	0	0	17
Total	0	2	32	7	4	0	0	45
13:00	0	0	7	2	0	0	0	9
13:15	0	1	10	2	1	0	0	14
13:30	0	0	3	1	0	0	0	4
13:45	0	0	8	1	0	0	0	9
Total	0	1	28	6	1	0	0	36
14:00	0	0	3	2	0	0	0	5
14:15	0	0	8	3	1	0	0	12
14:30	0	0	6	1	0	0	0	7
14:45	0	0	9	5	2	0	0	16
Total	0	0	26	11	3	0	0	40
15:00	0	0	7	1	0	0	0	8
15:15	0	0	4	2	0	0	0	6
15:30	0	0	6	3	1	0	0	10
15:45	0	1	10	3	0	0	1	15
Total	0	1	27	9	1	0	1	39
16:00	0	0	10	2	0	0	0	12
16:15	0	0	8	1	0	0	0	9
16:30	0	0	7	0	0	0	0	7
16:45	0	0	6	2	0	0	0	8
Total	0	0	31	5	0	0	0	36
17:00	0	0	6	5	0	0	0	11
17:15	0	0	11	4	0	0	0	15
17:30	0	1	11	3	0	0	0	15
17:45	0	0	14	0	0	0	0	14
Total	0	1	42	12	0	0	0	55
Day Total	2	5	411	110	23	0	2	553

Classified Vehicle Video Survey

Site: Cam 2 - Balfour Road/
Merton Road Junction
 Location: L.B. Merton
 Date: Monday 17th November 2014
 Time: 0600 - 1800
 Weather: Dry

2	P/C	M/C	Cars	LGV	MGV / HGV	Bus	Coach	Total
06:00	0	0	0	0	0	0	0	0
06:15	0	0	0	0	0	0	0	0
06:30	0	0	0	3	0	0	0	3
06:45	0	0	2	1	0	0	0	3
Total	0	0	2	4	0	0	0	6
07:00	0	0	3	1	1	0	0	5
07:15	2	0	3	0	0	0	0	5
07:30	0	0	2	2	0	0	0	4
07:45	0	0	7	0	0	0	0	7
Total	2	0	15	3	1	0	0	21
08:00	0	0	13	3	0	0	0	16
08:15	0	0	4	1	1	0	0	6
08:30	0	0	4	2	0	1	0	7
08:45	0	0	9	3	0	0	0	12
Total	0	0	30	9	1	1	0	41
09:00	0	0	5	2	0	0	0	7
09:15	0	0	7	0	0	0	0	7
09:30	0	0	3	0	0	0	0	3
09:45	0	0	8	0	0	0	0	8
Total	0	0	23	2	0	0	0	25
10:00	0	0	3	0	0	0	0	3
10:00	0	0	4	0	0	1	1	6
10:30	0	0	1	0	0	0	0	1
10:45	0	0	3	1	0	0	0	4
Total	0	0	11	1	0	1	1	14
11:00	0	0	2	0	0	0	0	2
11:15	0	1	4	0	0	0	0	5
11:30	0	0	8	1	0	1	0	10
11:45	0	0	6	3	0	0	0	9
Total	0	1	20	4	0	1	0	26
12:00	0	0	4	2	0	0	0	6
12:15	0	0	2	1	0	0	0	3
12:30	0	0	3	0	0	0	0	3
12:45	0	0	3	0	0	0	0	3
Total	0	0	12	3	0	0	0	15
13:00	0	0	1	1	0	0	0	2
13:15	0	0	1	2	1	0	0	4
13:30	0	0	5	2	0	0	0	7
13:45	0	0	3	1	0	0	0	4
Total	0	0	10	6	1	0	0	17
14:00	0	0	1	1	2	0	0	4
14:15	0	0	1	0	0	0	0	1
14:30	0	0	4	0	0	0	0	4
14:45	0	1	2	2	1	0	0	6
Total	0	1	8	3	3	0	0	15
15:00	0	0	8	2	0	0	0	10
15:15	0	0	3	0	0	0	0	3
15:30	0	0	4	0	0	0	0	4
15:45	0	0	2	1	0	1	0	4
Total	0	0	17	3	0	1	0	21
16:00	0	0	3	2	0	0	0	5
16:15	0	0	3	2	1	0	0	6
16:30	0	0	4	0	0	1	0	5
16:45	0	1	4	2	0	0	1	8
Total	0	1	14	6	1	1	1	24
17:00	0	0	7	1	0	0	0	8
17:15	0	0	2	1	0	0	0	3
17:30	0	0	2	1	0	0	0	3
17:45	0	0	6	1	1	0	0	8
Total	0	0	17	4	1	0	0	22
Day Total	2	3	179	48	8	5	2	247

Classified Vehicle Video Survey

Site: Cam 2 - Balfour Road/
Merton Road Junction
 Location: L.B. Merton
 Date: Thursday 20th November 2014
 Time: 0600 - 1800
 Weather: Dry

1	P/C	M/C	Cars	LGV	MGV / HGV	Bus	Coach	Total
06:00	1	0	0	0	0	0	0	1
06:15	1	0	6	1	0	0	0	8
06:30	1	0	3	0	0	0	0	4
06:45	0	0	4	0	1	0	0	5
Total	3	0	13	1	1	0	0	18
07:00	0	0	4	2	1	0	0	7
07:15	0	0	6	3	1	0	0	10
07:30	0	0	16	3	2	0	0	21
07:45	1	0	18	2	2	0	0	23
Total	1	0	44	10	6	0	0	61
08:00	0	0	8	2	0	0	0	10
08:15	2	0	15	2	0	0	0	19
08:30	1	1	10	2	1	0	0	15
08:45	0	0	12	4	0	0	0	16
Total	3	1	45	10	1	0	0	60
09:00	0	0	9	2	0	0	0	11
09:15	0	0	6	1	1	0	0	8
09:30	0	0	12	4	1	0	0	17
09:45	0	0	11	4	0	0	0	15
Total	0	0	38	11	2	0	0	51
10:00	0	0	8	1	0	0	0	9
10:00	0	0	9	2	2	0	0	13
10:30	0	1	7	1	0	0	0	9
10:45	0	1	2	1	1	0	0	5
Total	0	2	26	5	3	0	0	36
11:00	0	0	4	0	0	0	0	4
11:15	0	0	2	2	1	0	0	5
11:30	0	0	7	2	0	0	0	9
11:45	0	0	11	3	0	0	1	15
Total	0	0	24	7	1	0	1	33
12:00	0	0	7	2	0	0	0	9
12:15	0	0	11	3	0	0	0	14
12:30	0	1	9	3	0	0	0	13
12:45	0	0	5	1	0	0	0	6
Total	0	1	32	9	0	0	0	42
13:00	0	1	10	2	0	0	0	13
13:15	0	0	11	0	0	0	0	11
13:30	0	0	7	2	0	0	0	9
13:45	0	0	3	1	1	0	0	5
Total	0	1	31	5	1	0	0	38
14:00	0	0	7	0	0	0	0	7
14:15	0	0	5	3	0	0	0	8
14:30	0	0	8	2	0	0	0	10
14:45	0	0	9	1	0	0	0	10
Total	0	0	29	6	0	0	0	35
15:00	0	0	8	0	0	0	0	8
15:15	0	0	10	2	0	0	0	12
15:30	0	1	9	1	0	0	1	12
15:45	0	0	9	2	0	0	0	11
Total	0	1	36	5	0	0	1	43
16:00	0	0	12	4	0	0	0	16
16:15	0	0	8	4	0	0	0	12
16:30	0	0	9	1	0	0	0	10
16:45	0	1	9	2	0	0	0	12
Total	0	1	38	11	0	0	0	50
17:00	0	0	11	4	0	0	0	15
17:15	0	1	14	1	0	0	0	16
17:30	0	1	10	1	2	0	0	14
17:45	0	0	12	1	0	0	0	13
Total	0	2	47	7	2	0	0	58
Day Total	7	9	403	87	17	0	2	525

Classified Vehicle Video Survey

Site: Cam 2 - Balfour Road/
Merton Road Junction
 Location: L.B. Merton
 Date: Thursday 20th November 2014
 Time: 0600 - 1800
 Weather: Dry

2	P/C	M/C	Cars	LGV	MGV / HGV	Bus	Coach	Total
06:00	0	0	0	1	0	0	0	1
06:15	0	0	1	0	0	0	0	1
06:30	0	0	1	1	1	0	0	3
06:45	0	0	5	2	0	0	0	7
Total	0	0	7	4	1	0	0	12
07:00	0	0	7	1	1	0	0	9
07:15	0	0	4	3	0	0	0	7
07:30	1	1	2	1	0	0	0	5
07:45	1	0	6	1	0	0	0	8
Total	2	1	19	6	1	0	0	29
08:00	0	0	10	2	1	0	1	14
08:15	0	0	8	3	2	0	0	13
08:30	0	0	8	2	0	0	0	10
08:45	0	0	13	2	0	1	0	16
Total	0	0	39	9	3	1	1	53
09:00	0	0	5	0	0	0	0	5
09:15	0	0	6	1	0	1	0	8
09:30	0	0	4	2	1	0	0	7
09:45	0	0	9	2	1	0	0	12
Total	0	0	24	5	2	1	0	32
10:00	0	0	4	0	0	0	0	4
10:00	0	0	4	0	0	0	0	4
10:30	0	0	3	1	0	0	0	4
10:45	1	0	0	3	1	0	0	5
Total	1	0	11	4	1	0	0	17
11:00	0	1	7	1	1	0	0	10
11:15	0	0	6	3	0	0	0	9
11:30	0	0	2	1	0	0	0	3
11:45	0	0	4	2	1	0	0	7
Total	0	1	19	7	2	0	0	29
12:00	0	0	2	0	0	0	0	2
12:15	0	0	3	2	0	0	0	5
12:30	0	0	4	0	1	0	0	5
12:45	0	0	4	2	1	0	0	7
Total	0	0	13	4	2	0	0	19
13:00	0	0	4	2	0	0	0	6
13:15	0	1	2	1	0	0	0	4
13:30	0	0	7	0	0	0	0	7
13:45	0	1	2	1	0	0	0	4
Total	0	2	15	4	0	0	0	21
14:00	0	0	2	1	0	0	0	3
14:15	1	1	7	0	0	0	0	9
14:30	0	0	4	1	0	0	0	5
14:45	0	0	2	0	0	0	0	2
Total	1	1	15	2	0	0	0	19
15:00	0	1	3	1	0	0	0	5
15:15	0	1	2	0	0	0	0	3
15:30	0	0	4	2	0	0	0	6
15:45	0	0	1	1	0	0	0	2
Total	0	2	10	4	0	0	0	16
16:00	0	0	6	0	0	0	0	6
16:15	0	0	10	2	0	0	0	12
16:30	0	0	8	2	1	0	1	12
16:45	0	0	6	2	0	0	0	8
Total	0	0	30	6	1	0	1	38
17:00	1	0	7	1	0	0	0	9
17:15	0	1	9	1	2	0	0	13
17:30	0	0	1	2	0	0	0	3
17:45	0	0	2	1	0	0	0	3
Total	1	1	19	5	2	0	0	28
Day Total	5	8	221	60	15	2	2	313

Classified Vehicle Video Survey

Site: Cam 2 - Balfour Road/
Merton Road Junction
 Location: L.B. Merton
 Date: Saturday 29th November 2014
 Time: 0600 - 1800
 Weather: Dry

1	P/C	M/C	Cars	LGV	MGV / HGV	Bus	Coach	Total
06:00	0	0	1	0	0	0	0	1
06:15	0	0	3	0	0	0	0	3
06:30	0	0	1	0	0	0	0	1
06:45	0	0	1	0	0	0	0	1
Total	0	0	6	0	0	0	0	6
07:00	0	0	2	1	0	0	0	3
07:15	0	0	1	0	0	0	0	1
07:30	0	0	3	0	0	0	0	3
07:45	0	0	7	0	0	0	0	7
Total	0	0	13	1	0	0	0	14
08:00	0	0	5	1	0	0	0	6
08:15	0	0	7	2	0	0	0	9
08:30	0	0	11	4	0	0	0	15
08:45	1	0	14	2	0	0	0	17
Total	1	0	37	9	0	0	0	47
09:00	0	0	16	0	2	0	0	18
09:15	0	0	9	0	0	0	0	9
09:30	1	0	9	0	0	0	0	10
09:45	0	3	12	2	0	0	0	17
Total	1	3	46	2	2	0	0	54
10:00	0	0	14	2	0	0	0	16
10:00	1	0	7	0	0	0	0	8
10:30	0	0	8	0	0	0	0	8
10:45	0	0	15	1	0	0	0	16
Total	1	0	44	3	0	0	0	48
11:00	0	0	11	1	0	0	0	12
11:15	0	1	11	2	0	0	0	14
11:30	0	0	11	4	0	0	0	15
11:45	0	1	6	2	0	0	0	9
Total	0	2	39	9	0	0	0	50
12:00	0	1	15	0	0	0	0	16
12:15	0	0	7	1	1	0	0	9
12:30	0	0	11	0	0	0	0	11
12:45	0	0	16	3	0	0	0	19
Total	0	1	49	4	1	0	0	55
13:00	0	1	11	0	0	0	0	12
13:15	0	0	7	0	0	0	0	7
13:30	0	0	7	2	0	0	0	9
13:45	0	0	14	1	0	0	0	15
Total	0	1	39	3	0	0	0	43
14:00	0	1	12	0	0	0	0	13
14:15	0	0	8	0	0	0	0	8
14:30	1	0	10	2	0	0	0	13
14:45	0	0	8	4	0	0	0	12
Total	0	1	38	6	0	0	0	46
15:00	0	0	11	1	0	0	0	12
15:15	0	0	15	3	0	0	0	18
15:30	0	0	13	5	0	0	0	18
15:45	0	0	8	1	0	0	0	9
Total	0	0	47	10	0	0	0	57
16:00	0	0	5	0	0	0	0	5
16:15	0	0	11	1	0	0	0	12
16:30	0	0	15	1	1	0	0	17
16:45	0	1	6	1	0	0	0	8
Total	0	1	37	3	1	0	0	42
17:00	0	1	3	0	0	0	0	4
17:15	0	0	10	1	0	0	0	11
17:30	0	0	10	0	0	0	0	10
17:45	0	1	15	0	0	0	0	16
Total	0	2	38	1	0	0	0	41
Day Total	3	11	433	51	4	0	0	503

Classified Vehicle Video Survey

Site: Cam 2 - Balfour Road/
Merton Road Junction
 Location: L.B. Merton
 Date: Saturday 29th November 2014
 Time: 0600 - 1800
 Weather: Dry

2	P/C	M/C	Cars	LGV	MGV / HGV	Bus	Coach	Total
06:00	0	0	1	0	0	0	0	1
06:15	0	0	0	0	0	0	0	0
06:30	0	0	1	0	0	0	0	1
06:45	0	0	0	0	0	0	0	0
Total	0	0	2	0	0	0	0	2
07:00	0	0	1	0	1	0	0	2
07:15	0	0	0	0	0	0	0	0
07:30	0	0	1	0	0	0	0	1
07:45	0	0	3	0	0	0	0	3
Total	0	0	5	0	1	0	0	6
08:00	0	0	3	1	0	0	0	4
08:15	0	0	4	0	0	0	0	4
08:30	0	0	7	1	0	0	0	8
08:45	0	0	9	0	0	0	0	9
Total	0	0	23	2	0	0	0	25
09:00	0	0	8	0	0	0	0	8
09:15	0	0	2	0	0	0	0	2
09:30	0	0	6	0	0	0	0	6
09:45	0	0	3	0	0	0	0	3
Total	0	0	19	0	0	0	0	19
10:00	0	0	3	0	0	0	0	3
10:00	0	1	4	1	0	0	0	6
10:30	0	0	3	3	0	0	0	6
10:45	0	0	8	0	0	0	0	8
Total	0	1	18	4	0	0	0	23
11:00	0	0	8	0	0	0	0	8
11:15	0	0	3	1	0	0	0	4
11:30	0	0	3	0	0	0	0	3
11:45	0	0	5	0	0	0	0	5
Total	0	0	19	1	0	0	0	20
12:00	0	0	4	0	0	0	0	4
12:15	0	0	2	1	0	0	0	3
12:30	0	0	6	0	0	0	0	6
12:45	0	1	2	1	0	0	0	4
Total	0	1	14	2	0	0	0	17
13:00	0	0	4	0	0	0	0	4
13:15	0	0	7	1	0	0	0	8
13:30	1	0	3	3	0	0	0	7
13:45	0	1	3	0	0	0	0	4
Total	1	1	17	4	0	0	0	23
14:00	0	0	3	0	0	0	0	3
14:15	0	0	2	2	0	0	0	4
14:30	0	1	3	1	0	0	0	5
14:45	1	0	5	0	0	0	0	6
Total	1	1	13	3	0	0	0	18
15:00	0	0	5	0	0	0	0	5
15:15	0	0	4	1	0	0	0	5
15:30	0	0	4	3	0	0	0	7
15:45	0	1	5	0	0	0	0	6
Total	0	1	18	4	0	0	0	23
16:00	0	0	7	0	0	0	0	7
16:15	0	0	4	2	0	0	0	6
16:30	0	0	5	1	1	0	0	7
16:45	2	0	7	1	0	0	0	10
Total	2	0	23	4	1	0	0	30
17:00	0	0	2	1	0	0	0	3
17:15	0	0	0	0	0	0	0	0
17:30	0	0	3	0	0	0	0	3
17:45	0	0	1	0	0	0	0	1
Total	0	0	6	1	0	0	0	7
Day Total	4	5	177	25	2	0	0	213

Classified Vehicle Video Survey

Site: Cam 2 Area - Balfour Road/
Merton Road Junction
Location: L.B. Merton
Date: Tuesday 18th November 2014
Time: 0600 - 1800
Weather: Dry



This hourly observation is typical of the findings on each weekday of the survey on camera 2. Loading and unloading regularly occurs on the double yellow lines, occasionally causing a brief obstruction. In peak hours vehicles waiting to turn right cause queuing along Balfour Road.

Classified Vehicle Video Survey

Site: Cam 2 Area - Balfour Road/
Merton Road Junction
Location: L.B. Merton
Date: Saturday 29th November 2014
Time: 0600 - 1800
Weather: Dry



This hourly observation of the Saturday footage shows that loading and unloading still occasionally occurs. But any parking on the double yellow lines is more frequently for occupants to walk towards Merton Road.

Classified Vehicle Video Survey

Site: Cam 2 Area - Balfour Road/
Merton Road Junction
Location: L.B. Merton
Date: Sunday 23rd November 2014
Time: 0600 - 1800
Weather: Heavy Showers



This hourly observation of the Sunday footage shows that loading and unloading still occasionally occurs. But any parking on the double yellow lines is more frequently for occupants to walk towards Merton Road.

Video Observation Survey
 Site: Cam 2 Area - Balfour Road
 and Merton Road Junction
 Location: L.B. Merton
 Date: 17th, 23rd and 29th November 2014
 Time: 0600 - 1800
 Weather: Changeable

Vehicles illegally enter Balfour Road:

On Monday 17th 2 LGVs, 3 cars P/C and a M/C enter this road illegally, and this is typical of any weekday.



On Saturday 29th November 2 P/C's, 3 cars and 1 LGV enter this road illegally.



On Sunday 23rd November 1 car and 1 LGV enter this road illegally.



Video Observation Survey

Site: Cam 2 Area - Balfour Road
and Merton Road Junction
Location: L.B. Merton
Date: 17th, 23rd and 29th November 2014
Time: 0600 - 1800
Weather: Changeable

Vehicles illegally park on DYL on Balfour Road:

On Monday 17th November 3 cars, 10 LGV's, 1 MGV and 1 coach illegally park on DYL, and this is typical of any weekday.



Video Observation Survey

Site: Cam 2 Area - Balfour Road
and Merton Road Junction
Location: L.B. Merton
Date: 17th, 23rd and 29th November 2014
Time: 0600 - 1800
Weather: Changeable

Vehicles illegally park on DYL on Balfour Road:

On Sunday 23rd November, 6 cars and 2 LGV'S illegally park on DYL.



Video Observation Survey

Site: Cam 2 Area - Balfour Road
and Merton Road Junction
Location: L.B. Merton
Date: 17th, 23rd and 29th November 2014
Time: 0600 - 1800
Weather: Changeable

Vehicles illegally park on DYL on Balfour Road:
On Saturday 29th November, 5 cars, 3 LGV's and 1 MGV park on DYL.



Classified Vehicle Video Survey

Site: Cam 3 Area - Balfour Road
Location: L.B. Merton
Date: Tuesday 18th November 2014
Time: 0600 - 1800
Weather: Dry



This hourly observation is typical of the findings on each weekday of the survey on camera 3. The designated parking areas remain full almost constantly. If a vehicle leaves, the space is almost immediately filled.

Classified Vehicle Video Survey

Site: Cam 3 Balfour Road
Location: L.B. Merton
Date: Saturday 29th November 2014
Time: 0600 - 1800
Weather: Dry



This hourly observation of the Saturday footage shows that parking still remains busy. The occasional gaps materialize from about 17:30

Classified Vehicle Video Survey

Site: Cam 3 Balfour Road
Location: L.B. Merton
Date: Sunday 23rd November 2014
Time: 0600 - 1800
Weather: Heavy Showers



This hourly observation of the Sunday footage shows that parking still remains busy. The occasional gaps materialize from about 15:00.

Video Observation Survey

Site: Cam 3 Area - Balfour Road
Location: L.B. Merton
Date: 17th - 23rd November 2014
Time: 0600 - 1800
Weather: Some Heavy Showers

At peak times, traffic turning right onto Merton Road causes queueing along Balfour Road.



Vehicles regularly use the access area for parking and then occupants walk towards Merton Road.



Video Observation Survey

Site: Cam 3 Area - Balfour Road
Location: L.B. Merton
Date: 17th - 23rd November 2014
Time: 0600 - 1800
Weather: Some Heavy Showers

Vehicles dropping off and picking up for the tutoring centre, block the road and the entrance to the access area, as there is nowhere to pull over and park safely. On a weekday this occurs after 16:00. At the weekend, from about 10AM.

